

| Order No. | Catalogue No.          | Page(s)  | Order No. | Catalogue No.          | Page(s) | Order No. | Catalogue No.           | Page(s) | Order No. | Catalogue No.         | Page(s)       |
|-----------|------------------------|----------|-----------|------------------------|---------|-----------|-------------------------|---------|-----------|-----------------------|---------------|
| 5537870   | TCF125R4SL20MA         | V14      | 5538612   | TCF100408EPV36 WU40PH  | V23     | 5542020   | TCF180614HPV36 WU40PH   | V23     | 5548681   | TNGG160404FS WS10PT   | B83           |
| 5537871   | TCF127R4SL20MA         | V14      | 5538613   | TCF570R2SL50MH         | V9      | 5542327   | RNPJ10T3MOSMM WP40PM    | M25     | 5548682   | TNGG220408FS WS10PT   | B83           |
| 5537872   | TCF130R4SL20MA         | V14      | 5538614   | TCF580R2SL50MH         | V9      | 5542328   | RNPJ10T3MOSMM WP40PM    | M25     | 5548683   | VNGG160402FS WS10PT   | B95           |
| 5537873   | TCF135R4SL20MA         | V14, V16 | 5538615   | TCF590R2SL50MH         | V9      | 5542329   | RNPJ1204MOSMM WP40PM    | M33     | 5548684   | VNGG160401FS WS10PT   | B95           |
| 5537874   | TCF120R5SL20MA         | V17      | 5538616   | TCF600R2SL50MH         | V9      | 5542340   | RNPJ1204MOSMM WP40PM    | M33     | 5548685   | VNGG160404FS WS10PT   | B95           |
| 5537875   | TCF125R5SL20MA         | V17      | 5538617   | TCF610R2SL50MH         | V9      | 5542341   | RNPJ1605MOSMM WP40PM    | M38     | 5548686   | VNGG160408FS WS10PT   | B95           |
| 5537876   | TCF127R5SL20MA         | V17      | 5538618   | TCF620R2SL50MH         | V9      | 5542342   | RNPJ1605MOSMM WP40PM    | M38     | 5548687   | VNGG080404FS WS10PT   | B99           |
| 5537877   | TCF130R5SL20MA         | V17      | 5538619   | TCF630R2SL50MH         | V9      | 5542346   | WOEJ120712SRMM WP40PM   | M13     | 5548688   | VNGG080408FS WS10PT   | B99           |
| 5537878   | TCF135R5SL20MA         | V17, V19 | 5538630   | TCF640R2SL50MH         | V9      | 5542347   | WOEJ120712SRMM WP40PM   | M13     | 5549137   | CNGP120401 WS10PT     | B35           |
| 5537937   | TCF300R2SL32ME         | V8       | 5538631   | TCF650R2SL50MH         | V9      | 5542475   | TCF180508GCV34 WU25CH   | V20     | 5549138   | CNGP120402 WS10PT     | B35           |
| 5537938   | TCF310R2SL32ME         | V8       | 5538632   | TCF660R2SL50MH         | V9      | 5542476   | TCF180508GCV34 WU40PH   | V20     | 5549139   | CNGP120404 WS10PT     | B35           |
| 5537939   | TCF320R2SL32ME         | V9-10    | 5538633   | TCF670R2SL50MH         | V9      | 5542477   | TCF180508GCV36 WU25CH   | V21     | 5549190   | CNGP120408 WS10PT     | B35           |
| 5537940   | TCF330R2SL40ME         | V9       | 5538634   | TCF680R2SL50MH         | V9-10   | 5542478   | TCF180508GCV36 WU40PH   | V21     | 5549191   | DNGP150401 WS10PT     | B52           |
| 5537941   | TCF340R2SL40ME         | V9       | 5538635   | TCF570R3SL50MH         | V12     | 5542479   | TCF150512GPV34 WU25CH   | V22     | 5549192   | DNGP150402 WS10PT     | B52           |
| 5537942   | TCF350R2SL40ME         | V9       | 5538636   | TCF580R3SL50MH         | V12     | 5542600   | TCF150512GPV34 WU40PH   | V22     | 5549193   | DNGP150404 WS10PT     | B52           |
| 5537943   | TCF360R2SL40ME         | V9-10    | 5538637   | TCF590R3SL50MH         | V12     | 5542601   | TCF150512GPV34 WPK10CH  | V22     | 5549194   | DNGP150408 WS10PT     | B52           |
| 5537944   | TCF300R3SL32ME         | V11      | 5538638   | TCF600R3SL50MH         | V12     | 5542602   | TCF060203BCV34 WU25CH   | V20     | 5549195   | VNGP160401 WS10PT     | B96           |
| 5537945   | TCF310R3SL32ME         | V11      | 5538639   | TCF610R3SL50MH         | V12     | 5542603   | TCF150512GPV36 WU25CH   | V23     | 5549196   | VNGP160402 WS10PT     | B96           |
| 5537946   | TCF320R3SL32ME         | V12-13   | 5538640   | TCF620R3SL50MH         | V12     | 5542604   | TCF060203BCV34 WU40PH   | V20     | 5549197   | VNGP220404 WS10PT     | B96           |
| 5537947   | TCF330R3SL40ME         | V12      | 5538641   | TCF630R3SL50MH         | V12     | 5542605   | TCF150512GPV36 WU40PH   | V23     | 5549198   | VNGP220408 WS10PT     | B96           |
| 5537948   | TCF340R3SL40ME         | V12      | 5538642   | TCF640R3SL50MH         | V12     | 5542606   | TCF060203BCV36 WU25CH   | V21     | 5549206   | CNGP120402 WS10HT     | B35           |
| 5537949   | TCF350R3SL40ME         | V12      | 5538643   | TCF650R3SL50MH         | V12     | 5542607   | TCF060203BCV36 WU40PH   | V21     | 5549207   | CNGP120404 WS10HT     | B35           |
| 5537950   | TCF360R3SL40ME         | V12-13   | 5538644   | TCF660R3SL50MH         | V12     | 5542608   | TCF050204BPV34 WU25CH   | V22     | 5549208   | CNGP120408 WS10HT     | B35           |
| 5537951   | TCF300R4SL32ME         | V14      | 5538645   | TCF670R3SL50MH         | V12     | 5542609   | TCF050204BPV34 WU40PH   | V22     | 5549209   | DNGP150404 WS10HT     | B52           |
| 5537952   | TCF310R4SL32ME         | V14      | 5538646   | TCF680R3SL50MH         | V12-13  | 5542620   | TCF050204BPV34 WPK10CH  | V22     | 5549210   | DNGP150408 WS10HT     | B52           |
| 5537953   | TCF320R4SL32ME         | V15-16   | 5538647   | TCF570R4SL50MH         | V15     | 5542621   | TCF050204BPV36 WU25CH   | V23     | 5549211   | VNGP160401 WS10HT     | B96           |
| 5537954   | TCF330R4SL40ME         | V15      | 5538648   | TCF580R4SL50MH         | V15     | 5542622   | TCF050204BPV36 WU40PH   | V23     | 5549212   | VNGP220408 WS10HT     | B96           |
| 5537955   | TCF340R4SL40ME         | V15      | 5538649   | TCF590R4SL50MH         | V15     | 5542623   | TCF150406FCV34 WU25CH   | V20     | 5549945   | CNGG120404FS WU10HT   | B35           |
| 5537956   | TCF350R4SL40ME         | V15      | 5538650   | TCF600R4SL50MH         | V15     | 5542624   | TCF150406FCV34 WU40PH   | V20     | 5549946   | CNGG120408FS WU10HT   | B35           |
| 5537957   | TCF360R4SL40ME         | V15-16   | 5538651   | TCF610R4SL50MH         | V15     | 5542625   | TCF150406FCV36 WU25CH   | V21     | 5549947   | DNGG110402FS WU10HT   | B51           |
| 5537958   | TCF300R5SL32ME         | V17      | 5538652   | TCF620R4SL50MH         | V15     | 5542626   | TCF150406FCV36 WU40PH   | V21     | 5549948   | DNGG110404FS WU10HT   | B51           |
| 5537959   | TCF310R5SL32ME         | V17      | 5538653   | TCF630R4SL50MH         | V15     | 5542627   | TCF120412FPV34 WU25CH   | V22     | 5549949   | DNGG110408FS WU10HT   | B51           |
| 5537960   | TCF320R5SL32ME         | V18-19   | 5538654   | TCF640R4SL50MH         | V15     | 5542628   | TCF120412FPV34 WU40PH   | V22     | 5549990   | DNGG150402FS WU10HT   | B51           |
| 5537961   | TCF330R5SL40ME         | V18      | 5538655   | TCF650R4SL50MH         | V15     | 5542629   | TCF120412FPV34 WPK10CH  | V22     | 5549991   | DNGG150404FS WU10HT   | B51           |
| 5537962   | TCF340R5SL40ME         | V18      | 5538656   | TCF660R4SL50MH         | V15     | 5542640   | TCF120412FPV36 WU25CH   | V23     | 5549992   | DNGG150404FS WU10HT   | B51           |
| 5537963   | TCF350R5SL40ME         | V18      | 5538657   | TCF670R4SL50MH         | V15     | 5542641   | TCF120412FPV36 WU40PH   | V23     | 5549993   | DNGG150408FS WU10HT   | B51           |
| 5537964   | TCF360R5SL40ME         | V18-19   | 5538658   | TCF680R4SL50MH         | V15-16  | 5542642   | TCF070304CCV34 WU25CH   | V20     | 5549994   | DNGG150412FS WU10HT   | B51           |
| 5538204   | CNGG120404FS WS25PT    | B35      | 5538659   | TCF570R5SL50MH         | V18     | 5542643   | TCF070304CCV34 WU40PH   | V20     | 5549995   | DNGG150604FS WU10HT   | B51           |
| 5538205   | CNGG120408FS WS25PT    | B35      | 5538680   | TCF580R5SL50MH         | V18     | 5542644   | TCF070304CCV36 WU25CH   | V21     | 5549996   | DNGG150608FS WU10HT   | B51           |
| 5538206   | DNGG110402FS WS25PT    | B51      | 5538681   | TCF590R5SL50MH         | V18     | 5542645   | TCF070304CCV36 WU40PH   | V21     | 5549997   | SNGG120408FS WU10HT   | B70           |
| 5538207   | DNGG150404FS WS25PT    | B51      | 5538682   | TCF600R5SL50MH         | V18     | 5542646   | TCF070306CPV34 WU25CH   | V22     | 5549998   | VNGG160404FS WU10HT   | B83           |
| 5538208   | DNGG150408FS WS25PT    | B51      | 5538683   | TCF610R5SL50MH         | V18     | 5542647   | TCF070306CPV34 WU40PH   | V22     | 5549999   | VNGG160402FS WU10HT   | B95           |
| 5538209   | DNGG150604FS WS25PT    | B51      | 5538684   | TCF620R5SL50MH         | V18     | 5542648   | TCF070306CPV34 WPK10CH  | V22     | 5550000   | VNGG160401FS WU10HT   | B95           |
| 5538230   | DNGG150608FS WS25PT    | B51      | 5538685   | TCF630R5SL50MH         | V18     | 5542649   | TCF070306CPV36 WU25CH   | V23     | 5550001   | VNGG160404FS WU10HT   | B95           |
| 5538231   | TNGG160404FS WS25PT    | B83      | 5538686   | TCF640R5SL50MH         | V18     | 5542650   | TCF070306CPV36 WU40PH   | V23     | 5550002   | VNGG160408FS WU10HT   | B95           |
| 5538232   | VNGG160404FS WS25PT    | B95      | 5538687   | TCF650R5SL50MH         | V18     | 5544752   | WOEJ080412SRMM WP40PM   | M7      | 5550003   | VNGG080404FS WU10HT   | B99           |
| 5538233   | VNGG160408FS WS25PT    | B95      | 5538688   | TCF660R5SL50MH         | V18     | 5544753   | WOEJ080412SRMM WP40PM   | M7      | 5550004   | VNGG080408FS WU10HT   | B99           |
| 5538234   | VNGG080404FS WS25PT    | B99      | 5538689   | TCF670R5SL50MH         | V18     | 5545063   | XDPT110408PDSRMM WP40PM | J10     | 5550226   | TNMG160404UM WS10PT   | B88           |
| 5538235   | VNGG080408FS WS25PT    | B99      | 5538700   | TCF680R5SL50MH         | V18-19  | 5545064   | XDPT110408PDSRMM WP40PM | J10     | 5550228   | TNMG160408UM WS10PT   | B88           |
| 5538554   | TCF090305DCV34 WU25CH  | V20      | 5541817   | TCF040203ACV34 WU25CH  | V20     | 5545065   | XDCT110408PDERML WP40PM | J9      | 5550905   | HNGJ0704ANENLD WP40PM | H8, H16, H21  |
| 5538555   | TCF090305DCV34 WU40PH  | V20      | 5541818   | TCF040203ACV34 WU40PH  | V20     | 5548575   | CNGG120402FS WS10PT     | B35     | 5550906   | HNPJ0704ANSNGD WP40PM | H9, H17, H22  |
| 5538556   | TCF090305DCV36 WU25CH  | V21      | 5541819   | TCF040203ACV36 WU25CH  | V21     | 5548576   | CNGG120401FS WS10PT     | B35     | 5550907   | HNPJ0704ANSNHD WP40PM | H9, H17, H22  |
| 5538557   | TCF090305DCV36 WU40PH  | V21      | 5541840   | TCF040203ACV36 WU40PH  | V21     | 5548577   | CNGG120404FS WS10PT     | B35     | 5550908   | HNPJ0905ANSNGD WP40PM | H27, H34, H40 |
| 5538558   | TCF080308DPV34 WU25CH  | V22      | 5541841   | TCF040204APV34 WU25CH  | V22     | 5548578   | CNGG120408FS WS10PT     | B35     | 5550909   | HNPJ0905ANSNHD WP40PM | H28, H34, H40 |
| 5538559   | TCF080308DPV34 WU40PH  | V22      | 5541842   | TCF040204APV34 WU40PH  | V22     | 5548579   | CNGG120412FS WS10PT     | B35     | 5551088   | SNMT1205AZR31 WP40PM  | H55           |
| 5538600   | TCF080308DPV34 WPK10CH | V22      | 5541843   | TCF040204APV34 WPK10CH | V22     | 5548670   | DNGG110402FS WS10PT     | B51     | 5551152   | GX352733 WK12PG       | Y47           |
| 5538601   | TCF080308DPV36 WU25CH  | V23      | 5541844   | TCF040204APV36 WU25CH  | V23     | 5548671   | DNGG110404FS WS10PT     | B51     | 5551153   | GX352734 WK12PG       | Y47           |
| 5538602   | TCF080308DPV36 WU40PH  | V23      | 5541845   | TCF040204APV36 WU40PH  | V23     | 5548672   | DNGG110408FS WS10PT     | B51     | 5551154   | GX352735 WK12PG       | Y47           |
| 5538603   | TCF120405ECV34 WU25CH  | V20      | 5542002   | TCF210608HCV34 WU25CH  | V20     | 5548673   | DNGG150402FS WS10PT     | B51     | 5551155   | GX352737 WK12PG       | Y47           |
| 5538604   | TCF120405ECV34 WU40PH  | V20      | 5542003   | TCF210608HCV34 WU40PH  | V20     | 5548674   | DNGG150401FS WS10PT     | B51     | 5551156   | GX352738 WK12PG       | Y47           |
| 5538606   | TCF120405ECV36 WU25CH  | V21      | 5542004   | TCF210608HCV36 WU25CH  | V21     | 5548675   | DNGG150404FS WS10PT     | B51     | 5551157   | GX352739 WK12PG       | Y47           |
| 5538607   | TCF120405ECV36 WU40PH  | V21      | 5542005   | TCF210608HCV36 WU40PH  | V21     | 5548676   | DNGG150408FS WS10PT     | B51     |           |                       |               |
| 5538608   | TCF100408EPV34 WU25CH  | V22      | 5542006   | TCF180614HPV34 WU25CH  | V22     | 5548677   | DNGG150412FS WS10PT     | B51     |           |                       |               |
| 5538609   | TCF100408EPV34 WU40PH  | V22      | 5542007   | TCF180614HPV34 WU40PH  | V22     | 5548678   | DNGG150604FS WS10PT     | B51     |           |                       |               |
| 5538610   | TCF100408EPV34 WPK10CH | V22      | 5542008   | TCF180614HPV34 WPK10CH | V22     | 5548679   | DNGG150608FS WS10PT     | B51     |           |                       |               |
| 5538611   | TCF100408EPV36 WU25CH  | V23      | 5542009   | TCF180614HPV36 WU25CH  | V23     | 5548680   | SNGG120408FS WS10PT     | B70     |           |                       |               |