



Сверла со сменными режущими пластинами

Пластины для сверл Top Cut Plus™



Обработка отверстий • Сверла со сменными режущими пластинами

■ ХОМТ-34




● лучший выбор
○ альтернативный выбор

P	■	■	■	●	●	○
M	■	■	■	●	●	○
K	■	■	■	○	○	○
N	■	■	■	○	○	○
S	■	■	■	○	○	○
H	■	■	■	○	○	○

номер по каталогу	LI	W	D1	S	Re	THM	TN5515	TN6030	TN7015	TPC35
ХОМТ04Т10334	6,91	4,53	2,10	1,98	0,30	●	●	●	●	●
ХОМТ05020434	8,76	5,75	2,50	2,78	0,40	●	●	●	●	●
ХОМТ07030434	10,58	6,96	2,80	3,18	0,40	●	●	●	●	●
ХОМТ09Т30634	15,43	9,92	3,40	3,97	0,60	●	●	●	●	●
ХОМТ12Т30834	20,09	12,94	4,40	3,97	0,80	●	●	●	●	●
ХОМТ16050834	25,84	16,84	5,50	5,56	0,80	●	●	●	●	●

■ ХОМТ-35




● лучший выбор
○ альтернативный выбор

P	■	■	■	●	●	○
M	■	■	■	●	●	○
K	■	■	■	○	○	○
N	■	■	■	○	○	○
S	■	■	■	○	○	○
H	■	■	■	○	○	○

номер по каталогу	LI	W	D1	S	Re	THM	TN5515	TN6030	TN7015	TPC35
ХОМТ04Т10335	6,91	4,53	2,10	1,98	0,30	●	●	●	●	●
ХОМТ05020435	8,76	5,75	2,50	2,78	0,40	●	●	●	●	●
ХОМТ07030435	10,58	6,96	2,80	3,18	0,40	●	●	●	●	●
ХОМТ09Т30635	15,43	9,92	3,40	3,97	0,60	●	●	●	●	●
ХОМТ12Т30835	20,09	12,94	4,40	3,97	0,80	●	●	●	●	●
ХОМТ16050835	25,84	16,84	5,50	5,56	0,80	●	●	●	●	●

■ ХОМТ-36



● лучший выбор
○ альтернативный выбор

P	■	■	■	●	●	○
M	■	■	■	●	●	○
K	■	■	■	○	○	○
N	■	■	■	○	○	○
S	■	■	■	○	○	○
H	■	■	■	○	○	○

номер по каталогу	LI	W	D1	S	Re	TN6030	TN7015	TPC35
ХОМТ05020436	8,76	5,75	2,50	2,78	0,40	●	●	●
ХОМТ07030436	10,58	6,96	2,80	3,18	0,40	●	●	●
ХОМТ09Т30636	15,43	9,92	3,40	3,97	0,60	●	●	●
ХОМТ12Т30836	20,09	12,94	4,40	3,97	0,80	●	●	●
ХОМТ16050836	25,84	16,84	5,50	5,56	0,80	●	●	●